




WX479




WX479

| |  | Part No | Description | Substitute parts | Qty |
|--|---|----------|--------------------|------------------|-----|
| | 66 | 60050192 | Drive Spindle | | 1 |
| | 1 | 60039898 | Cable Protector | | 1 |
| | 2 | 50000833 | Cord clamp | | 1 |
| | 2 | 60039899 | Cord Clamp | 50000833 | 1 |
| | 3 | 60039900 | Screw | 60042358 | 2 |
| | 3 | 60042358 | Self Tapping Screw | | 2 |
| | 4 | 60039901 | Adjustment Knob | | 1 |
| | 5 | 60039902 | Depcorale Cover | | 1 |
| | 6 | 60039903 | Compression Spring | | 1 |
| | 7 | 60039904 | Steel Ball | | 1 |
| | 8 | 60039905 | Switch | | 1 |
| | 9 | 60040082 | Left/Right housing | | 1 |
| | 10 | 60039907 | Orientation Sleeve | | 4 |
| | 11 | 50003112 | E-ring | | 1 |
| | 11 | 60039908 | Retaining Ring | 50003112 | 1 |
| | 12 | 50000778 | Rubber-pin | | 2 |
| | 12 | 60039909 | Rubber Pin | 50000778 | 2 |
| | 13 | 50014807 | Nut | | 1 |
| | 13 | 60039910 | Nut | 50014807 | 1 |
| | 14 | 60039911 | Pin | | 1 |


WX479

|  | Part No | Description | Substitute parts | Qty |
|---|----------|--------------------|------------------|-----|
| 15 | 60039912 | Pendulum Plate | | 1 |
| 16 | 50010721 | Roller guide | | 1 |
| 16 | 60039913 | Pulley | 50010721 | 1 |
| 17 | 50010723 | Small shaft | | 1 |
| 17 | 60039914 | Pin | 50010723 | 1 |
| 18 | 50003110 | E-ring | | 2 |
| 18 | 60039915 | Retaining Ring | 50003110 | 2 |
| 19 | 60039916 | Capacitor | | 1 |
| 20 | 60039917 | Choke | | 1 |
| 21 | 60040083 | Stator | | 1 |
| 22 | 60039919 | Ball Bearing 607 | 60050657 | 1 |
| 23 | 60039920 | Brush Holder I | | 1 |
| 24 | 60039921 | Brush Holder II | | 1 |
| 25 | 60039922 | Carbon Brush(pair) | 60050134 | 1 |
| 25 | 60050134 | Carbon Brush(pair) | | 1 |
| 26 | 60039923 | Spiral Spring | | 2 |
| 27 | 60039924 | Screw | 60045553 | 4 |
| 27 | 60045553 | Screw ST2.9x10 | | 4 |
| 28 | 60040084 | Rotor | | 1 |
| 29 | 60039926 | Ball Bearing 608 | 60051431 | 1 |


WX479

| |  | Part No | Description | Substitute parts | Qty |
|--|---|----------|--------------------------------------|------------------|-----|
| | 29 | 60051431 | Ball Bearing 608 | | 1 |
| | 30 | 60039927 | Washer | | 1 |
| | 31 | 60039928 | Center Cover Set | | 1 |
| | 32 | 60039929 | Washer | | 3 |
| | 33 | 60039930 | Screw | 60050669 | 2 |
| | 33 | 60050669 | Self Tapping Screw | | 2 |
| | 34 | 60039931 | Needle Bearing | | 1 |
| | 35 | 60039932 | Pendulum Fork | | 1 |
| | 36 | 60039933 | Counterweight | | 2 |
| | 37 | 60039934 | Gear Set | | 1 |
| | 38 | 60039935 | Washer | | 1 |
| | 39 | 60039936 | Retaining Ring | 60051251 | 1 |
| | 39 | 60051251 | Retaining Ring | | 1 |
| | 40 | 60039937 | Roller | | 1 |
| | 41 | 60039938 | Guide Plate | | 1 |
| | 42 | 60039939 | Reciprocating Shaft Set | | 1 |
| | 43 | 50018944 | Spring | | 1 |
| | 43 | 60039940 | Compression Spring | 50018944 | 1 |
| | 44 | 60039941 | Metal &wood &aluminium Cutting Blade | | 1 |
| | 46 | 60039942 | Steel Spring | | 1 |

WX479

|  | Part No | Description | Substitute parts | Qty |
|---|----------|-----------------------|------------------|-----|
| 47 | 50031651 | Screw ST3.9x16 | | 12 |
| 47 | 60039943 | Screw | 50031651 | 12 |
| 48 | 60039944 | Fore Cover | | 1 |
| 49 | 60039945 | Screw | 60050250 | 4 |
| 49 | 60050250 | Screw | | 4 |
| 50 | 50014801 | Press plate | | 1 |
| 50 | 60039946 | Press Plate | 50014801 | 1 |
| 51 | 60039947 | Screw | | 1 |
| 52 | 60039948 | Power cord | 60052567 | 1 |
| 52 | 60052567 | Cord & Plug | | 1 |
| 53 | 60039951 | Spanner | | 1 |
| 55 | 50014798 | Base plate | | 1 |
| 55 | 60040085 | Base Plate | 50014798 | 1 |
| 56 | 60040086 | Screw | | 2 |
| 57 | 60040087 | Steel Plate | | 1 |
| 58 | 60040088 | Saw Box | | 1 |
| 59 | 60040089 | Dust Tube | | 1 |
| 60 | 60040090 | Splinter Protector | | 1 |
| 61 | 60040091 | Variable Speed Board | | 1 |
| 62 | 60040092 | Speed Adjustment Knob | | 1 |

WX479

|  | Part No | Description | Substitute parts | Qty |
|---|----------|--------------------------|------------------|-----|
| 63 | 60040093 | Guide Plate | | 1 |
| 64 | 60040094 | Screw | | 6 |
| 65 | 60040097 | Power supply board | | 1 |
| 101 | 60039954 | Brush Holder Assembly I | | 1 |
| 102 | 60040095 | Rotor Set | | 1 |
| 103 | 60039956 | Brush Holder Assembly II | | 1 |
| 104 | 60040096 | Base Assembly | | 1 |
| 105 | 60045330 | Blade guide assemble | | 1 |
| F1 | 60041201 | Color box for WX479 | | 1 |